GOVERNMENT OF KARNATAKA

BANGALORE URBAN DISTRICT

Office of the Assistant Executive Engineer P.R.Engineering Sub-Division Bangalore East Taluk, K.R.Puram Bangalore-560036

No:AEE/PRE Sub-dn/AE-II/2017-18

Dated:27/10/2017

To Whom It May Concern

Building Stability / Safety Certificate

- Ref:- 1) Structural and construction details provided by ANAND CONSTRUCTIONS vide document Dt 24TH MARCH 2017
 - 2) Certificate by Building stability issued by M/S ANAND CONSTRUCTIONS Dt $17^{\rm TH}$ MARCH 2017.
 - Certificate Building stability issued by Government of Karnataka Approved Engineer B. BASAVARAJ Dt 10/08/2017.
 - Building stability Certificate issued by BIDARAHALLI GRAM PANCHAYATH GOVT OF KARNATAKA Dt 28 /08/2017.
 - 5) BUILDING PLAN SANCTIONED BY BIDARAHALLI PANCHAYATH GOVT OF KARNATAKA .

The undersigned inspected MARUTHI VIDYALAYA school building located in 17/2, Kada Agrahara, Bidarahalli Hobli, Bengaluru 560077 on 26/10/2017 and verified the structural ,construction and dimensional details provided by M/S ANAND CONSTRUCTIONS, Dt 24 MARCH 2017 and sanctioned building plan. Further the Building, Classroom, Boys toilets, Girls toilets, Laboratories, Security room, Generator room, Stair Cases, Entries & Exits, etc., were inspected to ascertain the safety and stability aspects for school children.

The building constructed as per references mentioned above is stable and safe for the purposes of school and school children.

Dt: 27/10/2017 Station: BANGALORE The state of the s

Phraosaly

PRINCIPAL

Maruthi Vidyalaya EHPS

17 /2, Kada Agrahara,

Bidarahalli Hobli,